



**210' DP-1 OSV DWT 2,127
CAPT WOODROW**



DIMENSIONS & DOCUMENTATION

Length Overall:	210 Ft 64 M	Beam:	48 Ft 14.6 M	Depth:	18 Ft 5.5 M
GRT (ITC):	1,395	Net:	418	Max Draft:	16 Ft 4.8 M
Classification:	ABS	Flag:	US	Min Draft:	
Classification ID:	09636608	O. N.	1063439	Year Built:	2000
IMO:	9203837				
Notations:	✘A1, Domestic Service, ✘AMS				
Certifications	Subchapter L				

PERFORMANCE

Maximum Speed:	12.0 knots	Fuel Consumption:	150 gal/hr	568 l/hr
Cruising Speed:	10.0 knots	Fuel Consumption:	120 gal/hr	454 l/hr

MACHINERY

Main Engines:	2 x EMD 16-545 E	Total Horsepower:	4,000 BHP
Main Propulsion:	Convention Wheels	Total Horsepower:	4,000 BHP
Main Generators:	2 x GM 8v-71	Total Rating:	250 kW
Bow Thrusters:	1	Total Horsepower:	600 BHP
Power Generation	480V/60Hz		

CAPACITIES & DISCHARGE RATES

Deadweight:	2,127 Lt	2,161 Mt	Cargo Deck Area:	136 ft x 40 ft	5,440 Ft ²
Deck Strength:	1,080 lbs/ft ²	5.25 t/m ²		41.5 M X 12.2 M	506.3 M ²
Drill/Rig Water:	42,000 USG	159 M ³	Discharge Rate:	750 GPM	170 M ³ /hr
Fuel:	190,000 USG	719.23 M ³	Discharge Rates:	750 GPM	170 M ³ /hr
Liquid Mud:	3,300 Bbls	524 M ³	Discharge Rates:	1,000 GPM	227 M ³ /hr
Dry Bulk:	8,000 ft ³	226.5 M ³	Discharge Rates:	1,000 ft ³ /hr	28 M ³ /hr
Potable Water:	35,000 USG	132.5 M ³			80 psi
Fire Monitor:	1 x 3,000 GPM				

ELECTRONICS

1 X Beier IVCS 4000 DP-1 System, Full Joy Stick Mode, 2 DGPS Receivers, MDL Fan Beam, 1 gyro compass, 2 wind sensors, Radars (2), VHF Radios(2), Bridge Navigation Watch Alarm System, GMDSS, Rose Point Navigators (2)

ACCOMMODATIONS

Accommodations for 24 persons in the following room configurations:
 2 each 1 person room 4 each 4 person rooms 1 each 6 person rooms

SPECIAL FEATURES

- Complete complement of Safety Standby Equipment, Scramble Net, Life Jackets, Blankets, Etc.

NOTICE: The data contained herein is provided for convenience of reference to allow users to determine the suitability of the Company's equipment. The data may vary from the current condition of equipment which can only be determined by physical inspection. Company has exercised due diligence to insure that the data contained herein is reasonably accurate. However, Company does not warrant the accuracy or completeness of the data. In no event shall Company be liable for any damages whatsoever arising out of the use or inability to use the data contained herein.